

Date: User:

Tuesday, 15/08/2006 7:17:00 AM

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 28158

Estimate Number

: 11032

P.O. Number

A14:

This Issue

Prsht Rev.

First Issue

Written By

Previous Run

: 15/08/2006

: NC

: NA

S.O. No. : HIA .

Type

: PURCHASED PARTS

: 25710

Checked & Approved By

Comment

MS21043-3 was MS21042L3 : Est D 05.03.30

Drawing Name

: BRACKET ASSEMBLY

Part Number

Material

KJ/JLM

Drawing Number

: D2803043 - D2803 REV B

: N/A

Project Number Drawing Revision

: NA

Due Date

: 08/09/2006

Qty:

8 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 D28031

STA 84 Bracket



Comment: Qty.:

1.0000 Each(s)/Unit Total + 8.0000 Each(s)

STA 84 BRACKET

Pick:

Qty 1

D28053

Part Number

Description

Bracket

Batch

D2803-1

2.0



1.0000 Each(s)/Unit Total:

8.0000 Each(s)

STOP

Pick:

Qty Part Number

D2805-3

Description Stop

3.0

1 D2809



1.0000 Each(s)/Unit

Total:

8.0000 Each(s)

Comment: Qty.:

Comment; Qty.:

Bushing

Pick:

Qty Part Number Deścription

D2809

Bushing

B21617 V

Press D2805-3 into arm as per Dwg D2803

SB 06/09/04

1806/08/31

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR	: Yes	No DQ	A:	Date:	Date:
•						QA: N	/C Close	d:	_ Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR	3)			
DATE	STEP	Description of NC			tion B		Verific	ation	n Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
				·					**************************************	
				٠						
1										
							-			

NOTE: Date & initial all entries

Tuesday, 15/08/2006 7:17:00 AM Date: Linda Lacelle User: **Process Sheet Drawing Name: BRACKET ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D2803043 Job Number: 28158 Job Number: Seq. #: Description: Machine Or Operation: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 .QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE POWDER COATING POWDER COATING 5.0 **Comment: POWDER COATING** Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 6.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION SMALL & MEDIUM FAB RESOURCE 1 7.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Press D2809 into arm as per Dwg D2803 AN3C16A Bolt 8.0 Comment: Qty.: 16.0000 Each(s) 2.0000 Each(s)/Unit Total: **Bolt** Pick: Qty Part Number Description Batch 4/06/08/31 AN3C16A **Bolt** 9.0 MS210433 Comment: Qtv.: 2.0000 Each(s)/Unit Total: 16.0000 Each(s) Nut Pick: Qtv Part Number Description Batch 2 MS21043-3 10.0 NAS1515H3 Comment: Qty.: 4.0000 Each(s)/Unit Total: 32.0000 Each(s) Washer Pick: Qty Part Number Description NAS1515H3 Washer LPS-3 Corrosion Spray in Page 2

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector				
06.05.05	4.0	Derm. Change / Perm. Change					0609.05				

Part No:	_ PAR #:	Fault Category:	NCR: Yes No	DQA:	Date: <u>~/</u>	109/0x
			QA: N/C C	losed:	Date:	

NCR:	:		WORK ORD	ER NON-CONFORMAN	CE (NCR)			
DATE		STEP Description of NC Section A		Corrective Action Section B			Annessal	
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
	**							

NOTE: Date & initial all entries


Date: Tuesday, 15/08/2006 7:17:01 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BRACKET ASSEMBLY Job Number: 28158 Part Number: D2803043 Job Number: Seq. #: **Machine Or Operation:** Description: 101472 Spray LPS-3 on Bolt Shaft, not on thread as per Dwg D2803 SMALL & MEDIUM FAB RESOURCE 1 11.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per Dwg D2803. INSPECT WORK TO CURRENT STEP 12.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 13.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location 14.0 DOCUMENT CONTROL Comment: DOCUMENT CONTROL Inspection Level 21 U de Pros Job Completion



Dart Ae	rospace	Ltd					
W/O:		WORK ORDE	R CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	-						
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A :	_ Date: _	
			QA:	N/C Close	d:	_ Date: _	
NCR:		WORK ORDER NON-C	ONFORMANCE (NC	R)			

NCR:		,	WORK ORDER NON-CONFORMANCE (NCR)									
DATE		Description of NC		Corrective Action Section B			A					
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector				
	7 7											

NOTE: Date & initial all entries



MACHINE PER DRAWING FILE "D2803-A1.DWG" MATERIAL: 6061-T6 (QQ-A-200/8) OR (QQ-A-250/11) 0.500 THICK DEBURR TO LEAVE RO.030 - 0.063 ON ALL EDGES FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.